Mercedes-Benz Trailer Spare Parts - LOCATION : SJAELLAND - 4180 SORO

General characteristics

Brand	Mercedes-Benz
Subcategory	Axle
Condition	Used



Description

3 AXEL CHASSIS FROM DAMAGED TRAILER. AXEL TYPE.TE5/8C7-9. SERIAL NO.H263706. VARIANT NO.0 360 540 447. TDB NO.0571. WITH 385 X 65 X 22,5 TIRE.